

Per the Illinois Compiled Statutes, 625 ILCS 5/11-208.6 Automated Traffic Law Enforcement System:


(k-7) A municipality or county operating an automated traffic law enforcement system shall conduct a statistical analysis to assess the safety impact of each automated traffic law enforcement system at an intersection following installation of the system. The statistical analysis shall be based upon the best available crash traffic and other date, and shall cover a period of time before and after installation of the system sufficient to provide a statistically valid comparison of safety impact. The statistical analysis shall be consistent with professional judgment and acceptable industry practice. The statistical analysis also shall be consistent with the data required for valid comparisons of before and after conditions and shall be conducted within a reasonable period following the installation of the automated traffic law enforcement system. The statistical analysis required by this subsection (k-7) shall be made available to the public and shall be published on the website of the municipality or county. If the statistical analysis for the 36-month period following installation of the system indicates that there has been an increase in the rate of accidents at the approach to the intersection monitored by the system, the municipality or county shall undertake additional studies to determine the cause and severity of the accidents, and may take any action that it determines is necessary or appropriate to reduce the number or severity of the accidents at that intersection.

A Red Light Running (RLR) Photo Enforcement System was installed at the intersection of US Rte. 12/20/45 (Mannheim) at US Rte. 20 (Lake) on September 15, 2008, after finding limited success with other attempted measures to promote safer driving and improve compliance with traffic laws. The following statistical analysis was performed through 2015. Calendar year 2016 was not included as the Illinois Department of Transportation (IDOT) has not yet completed collecting all data. The statistical analysis will be updated annually, as collected data becomes available from IDOT.



US Rte. 12/20/45 (Mannheim) at US Rte. 20 (Lake) Melrose Park, IL

- RLR Photo Enforcement System monitors violations occurring on the northbound and eastbound approaches of the intersection
- RLR Photo Enforcement System installed: September 15, 2008






US Rte. 12/20/45 (Mannheim) at US Rte. 20 (Lake), Northbound Approach



US Rte. 12/20/45 (Mannheim) at US Rte. 20 (Lake), Southbound Approach





US Rte. 12/20/45 (Mannheim) at US Rte. 20 (Lake), Westbound Approach



US Rte. 12/20/45 (Mannheim) at US Rte. 20 (Lake), Westbound Approach





Data was obtained from the Illinois Department of Transportation's website <u>www.gettingaroundillinois.com</u>.

US Rte. 12/20/45 (Mannheim) at US Rte. 20 (Lake) (Northbound)

- 38,900 (2007)
- 36,000 (2009)
- 36,300 (2011)
- 23,700 (2013)






Data was obtained from the Illinois Department of Transportation's website <u>www.gettingaroundillinois.com</u>.

US Rte. 12/20/45 (Mannheim) at US Rte. 20 (Lake) (Southbound)

- 39,100 (2005)
- 39,800 (2007)
- 39,500 (2009)
- 35,900 (2011)
- 23,700 (2013)






Data was obtained from the Illinois Department of Transportation's website <u>www.gettingaroundillinois.com</u>.

US Rte. 12/20/45 (Mannheim) at US Rte. 20 (Lake) (Eastbound)

- 25,700 (2005)
- 25,700 (2006)
- 22,500 (2007)
- 26,600 (2009)
- 24,800 (2010)
- 32,600 (2013)





Data was obtained from the Illinois Department of Transportation's website <u>www.gettingaroundillinois.com</u>.

US Rte. 12/20/45 (Mannheim) at US Rte. 20 (Lake) (Westbound)

- 21,000 (2006)
- 24,200 (2010)
- 22,300 (2014)





Crash History and Analysis

• Table 1 includes crash data obtained from the Illinois Department of Transportation, detailing angle, turning, rear-end, and other type crashes occurring at the intersection pre/post RLR Photo Enforcement System installation.

	Crashes								
	Rear-En	d (% of	Angle	(% of	Turning	g (% of	Other	' (% of	
	Tot	al)	Tot	al)	Tota	al)	То	tal)	Total
2005	22	64.7%	0	0.0%	9	26.5%	3	8.8%	34
2006	11	37.9%	2	6.9%	9	31.0%	7	24.1%	29
2007	22	48.9%	3	6.7%	13	28.9%	7	15.5%	45
Total	55	50.9%	5	4.6%	31	28.7%	17	15.7%	108
2005-2007									
Average	18	.3	1.	7	10.	3	5	.7	36.0

ALL INTERSECTION APPROACHES

		RLR C	amera Ins	tallation:	Septembe	er 15, 200	8		
2008	23	67.6%	1	2.9%	3	8.8%	7	20.6%	34
						•			
2009	15	88.2%	2	11.8%	0	0.0%	0	0.0%	17
2010	19	82.6%	2	8.7%	2	8.7%	0	0.0%	23
2011	13	65.0%	1	5.0%	2	10.0%	4	20.0%	20
2012	13	76.5%	0	0.0%	2	11.8%	2	11.8%	17
2013	17	77.3%	0	0.0%	5	22.7%	0	0.0%	22
2014	17	73.9%	1	4.3%	2	8.7%	3	13.0%	23
2015	24	70.6%	1	2.9%	5	14.7%	4	11.8%	34
Total	118	75.6%	7	4.5%	18	11.5%	13	8.3%	156
2009-2015									
Average	16.	.8	1.	0	2.0	5	1	.8	22.3

Other indicates the following: Pedestrian, Pedal Cyclist, Fixed Object, Sideswipe, Head-On and Unknown

Table 1

DISCLAIMER: The motor vehicle crash data referenced herein was provided by the Illinois Department of Transportation, based upon information derived from multiple sources. Any conclusions drawn from analysis of the aforementioned data are the sole responsibility of the data recipient(s). Additionally, for coding years 2015 to present, the Bureau of Data Collection uses the exact latitude/longitude supplied by the investigating law enforcement agency to locate crashes. Therefore, location data may vary in prior years, since the data prior to 2015 was physically located by bureau personnel. Given the subjective nature of the reporting process, the modifications in the incident locating protocols and the changes to the crash reporting thresholds effective 2009, the Village of Melrose Park acknowledges the potential for discrepancies in the final conclusions drawn.



Crash History and Analysis (continued)

• Table 2 includes crash data obtained from the Illinois Department of Transportation, detailing angle, turning, rear-end, and other-type crashes occurring at the intersection on the northbound and eastbound approaches only, pre/post RLR Photo Enforcement System installation.

NORTHBOUND/EASTBOUND APPROACHES ONLY (PHOTO ENFORCED APPROACHES)

	Crashes								
	Rear-Ei	nd (% of	Angle	e (% of	Turnir	ng (% of	Othe	r (% of	
	То	tal)	Tc	otal)	To	otal)	Τc	otal)	Total
2005	15	68.2%	0	0.0%	4	18.2%	3	13.6%	22
2006	4	36.3%	1	9.1%	3	27.3%	3	27.3%	11
2007	10	43.5%	2	8.7%	7	30.4%	4	17.4%	23
Total	29	51.8%	3	5.3%	14	25.0%	10	17.8%	56
2007-2007									
Average	9	.7	1	.0	4	ł.7	3	3.3	18.7

		RLR Ca	amera Ins	tallation	Septembe	er 15, 2008	3		
2008	10	66.7%	1	6.7%	2	13.3%	2	13.3%	15
2009	10	100.0%	0	0.0%	0	0.0%	0	0.0%	10
2010	11	84.6%	1	7.7%	1	7.7%	0	0.0%	13
2011	8	80.0%	0	0.0%	0	0.0%	2	20.0%	10
2012	6	85.7%	0	0.0%	0	0.0%	1	14.3%	7
2013	8	72.7%	0	0.0%	3	27.3%	0	0.0%	11
2014	13	81.2%	0	0.0%	1	6.2%	2	12.5%	16
2015	11	73.3%	0	0.0%	3	20.0%	1	6.7%	15
Total	67	81.7%	1	1.2%	8	9.7%	6	7.3%	82
2009-2015									
Average	9.	6	0.	1	1.	1	0	.8	11.7

Other indicates the following: Pedestrian, Pedal Cyclist, Fixed Object, Sideswipe, Head-On and Unknown

Table 2

DISCLAIMER: The motor vehicle crash data referenced herein was provided by the Illinois Department of Transportation, based upon information derived from multiple sources. Any conclusions drawn from analysis of the aforementioned data are the sole responsibility of the data recipient(s). Additionally, for coding years 2015 to present, the Bureau of Data Collection uses the exact latitude/longitude supplied by the investigating law enforcement agency to locate crashes. Therefore, location data may vary in prior years, since the data prior to 2015 was physically located by bureau personnel. Given the subjective nature of the reporting process, the modifications in the incident locating protocols and the changes to the crash reporting thresholds effective 2009, the Village of Melrose Park acknowledges the potential for discrepancies in the final conclusions drawn.



Comparison of annual averages shows the total number of crashes decreasing by 38.0% at the intersection for all approaches and by 37.4% on the northbound and eastbound (photo enforced) approaches post-camera installation.

The US Department of Transportation Project Development and Design Manual states that turning, angle or head-on crashes have a number of probable crash causes, to include:

- Large volumes of left /right turns
- Large total intersection volume
- Excessive speed on approaches
- Inadequate traffic control devices
- Poor visibility of signals

While red light cameras cannot truly decrease the volume of cars entering the intersection, speed and proximity of vehicles entering an intersection or the amount of turning traffic volume, red light cameras and red-light camera photo enforcement warning signs have the ability to reduce traffic crashes and improve compliance with traffic control devices.



Adjudication Experience

RLR camera violations are contested and adjudicated through an administrative hearing conducted each month. Adjudication data for the Village's Automated Enforcement Program is shown below in Table 3. Data compiled is not intersection specific, rather totals for the program as a whole.

VILLAGE OF M	ELROSE PARK ADJUD	ICATION FOR					
AUTOMATED PHOTO ENFORCEMENT PROGRAM							
YEAR / TOTALS	LIABLE	NOT LIABLE					
2008	961	395					
2009	730	276					
2010	428	184					
2011	349	107					
2012	435	132					
2013	312	108					
2014	368	137					
2015	770	225					
2016	679	255					
2017	431	160					
YEAR TO DATE TOTAL:	5,463	1,979					

*Adjudication data provided thru August 2017

Table 3

The high-quality video footage and photographic evidence produced by the enforcement system is a contributing factor in a majority of the contested RLR violations being upheld by the Hearing Officer. The police officers assigned to review and approve/reject potential violations are vigilant in applying the same officer discretion and criteria they would if issuing an in-person citation, resulting in only highly prosecutable violations being mailed out.